









































<u>MOULDING</u>	<u>Code/Size</u>	<u>Poplar</u>	<u>Red Oak</u>	<u>H. Maple</u>	<u>Other</u>
<b>Colonial Casing</b> 	<b>E201</b> 2 3/4 x 3/4 <b>E221</b> 3 1/2 x 3/4	2.41 2.90	2.71 3.26	4.43	We have other species available in some of the profiles. Please inquire.
<b>Colonial Baseboard</b> 	<b>E601</b> 4 1/4 x 11/16 <b>E621</b> 5 1/4 x 11/16	3.39 4.04	3.81 4.55	6.24	
<b>Tudor Casing</b> 	<b>E202</b> 2 3/4 x 3/4 <b>E222</b> 3 1/2 x 3/4	2.41 2.90	2.71 3.26		
<b>Tudor Baseboard</b> 	<b>E602</b> 4 1/4 x 11/16 <b>E622</b> 5 1/4 x 11/16 <b>E632</b> 7 1/4 x 11/16	3.39 4.04 5.47	3.81 4.55 6.15		
<b>Bevelled Casing</b> 	<b>E203</b> 2 3/4 x 3/4	2.41	2.71		
<b>Bevelled Baseboard</b> 	<b>E603</b> 4 1/4 x 11/16	3.39	3.81		
<b>Provincial Casing</b> 	<b>E224</b> 3 1/2 x 3/4	2.90	3.26		
<b>Provincial Baseboard</b> 	<b>E604</b> 4 1/4 x 11/16 <b>E624</b> 5 1/4 x 11/16 <b>E634</b> 7 1/4 x 11/16	3.39 4.04 5.47	3.81 4.55 6.15		
<b>Step Casing</b> 	<b>E227</b> 3 1/2 x 3/4	2.90			
<b>Step Baseboard</b> 	<b>E627</b> 5 1/4 x 11/16 <b>E637</b> 7 1/4 x 11/16	4.04 5.47			
<b>E128 Door Stop</b> <b>E130 Door Stop</b> <b>E136 Door Stop</b>   	<b>E128</b> 1 3/8 x 3/8 <b>E130</b> 1 1/4 x 3/8 <b>E136</b> 1 1/2 x 3/8	0.95 0.95 0.98	1.06 1.06 1.11		
<b>E137 Door Stop</b> <b>E102 Backband</b> <b>E127 Bevel Backband</b>   	<b>E137</b> 1 1/2 x 3/8 <b>E102</b> 1 1/4 x 3/4 <b>E127</b> 1 1/4 x 3/4	0.98 1.25 1.25	1.40 1.40	2.30	



6 Peacock Bay, St Catharines, Ontario, Canada L2M 7N8  
 Phone: (905) 937-3030 Fax: (905) 937-6799  
 Website: www.eastwoodspecialties.ca



















<u>MOULDING</u>		<u>Code/Size</u>	<u>Poplar</u>	<u>Red Oak</u>	<u>H. Maple</u>	<u>Other</u>
E616 Quarter Round 	E618 Shoe Mould 	<u>E616</u> 3/4 x 5/8  <u>E618</u> 1 1/8 x 1/2	0.79  1.25	0.89  1.40	1.46  2.30	
 Door Jamb		<u>EJ463</u> 4 5/8 x 3/4  <u>EJ663</u> 6 5/8 x 3/4	3.53  5.01			
 Header		<u>E280</u> 4 13/16 x 1 3/4	11.34			
 Chair Rail		<u>E275</u> 2 3/4 x 13/16	2.51	2.82	4.62	
 Chair Rail		<u>E276</u> 1 1/2 x 1 1/8	2.46	2.76	4.52	
 Chair Rail		<u>E277</u> 2 1/2 x 1 1/8	3.45	3.88	6.36	
 Chair Rail		<u>E279</u> 3 x 1 1/4	6.62	7.44	12.18	
 Bar Rail		<u>E780</u> 5 1/4 x 1 3/4	11.40	13.95	18.30	
		<u>E970</u> 8 1/2 x 7/8	7.25	8.15	13.34	

We have other species available in some of the profiles. Please inquire.

<u>MOULDING</u>	<u>Code/Size</u>	<u>Poplar</u>	<u>Red Oak</u>	<u>H. Maple</u>	<u>Other</u>
Crown Mould 	<b>E980</b> 1 5/8 x 11/16	1.49	1.67	2.74	We have other species available in some of the profiles. Please inquire.
Crown Mould 	<b>E982</b> 2 3/8 x 3/4	2.09	2.35	3.85	
Cove Mould 	<b>E983</b> 3 1/2 x 3/4	2.90	3.26	5.34	
Crown Mould 	<b>E921</b> 4 1/4 x 3/4	3.10	3.49	5.71	
Crown Mould 	<b>E984</b> 4 1/4 x 3/4	3.39	3.81	6.24	
Crown Mould 	<b>E985</b> 5 1/8 x 13/16	3.96	4.45	7.28	
Cove Mould 	<b>E986</b> 5 1/8 x 7/8	3.96	4.45	7.28	
Crown Mould 	<b>E987</b> 4 1/2 x 13/16	3.62	4.07	6.66	
Shaker Flat Mould 	<b>E910</b> 3 5/16 x 11/16	2.84	3.19	5.22	
Shaker Cove Mould 	<b>E912</b> 3 1/2 x 7/8	2.90	3.26	5.34	
Shaker Cove Mould 	<b>E922</b> 4 7/8 x 7/8	3.79	4.27	6.95	
Library Cove Mould 	<b>E931</b> 7 x 1 1/8	8.44	9.50	15.54	

















6 Peacock Bay, St Catharines, Ontario, Canada L2M 7N8  
 Phone: (905) 937-3030 Fax: (905) 937-6799  
 Website: www.eastwoodspecialties.ca

<b>MOULDING</b>			<b>Code/Size</b>	<b>Poplar</b>	<b>Red Oak</b>	<b>H. Maple</b>	<b>Other</b>
<b>Dentil Crown Mould</b> 			<b>E974</b> 4 1/8 x 13/16	3.34	3.76	6.15	We have other species available in some of the profiles. Please inquire.
<b>Counter Trim</b> 			<b>E170</b> 1 1/2 x 3/4	1.44	1.62	2.64	
<b>E105 Bead Mould</b> 	<b>E106 Bead Mould</b> 	<b>E105</b> 3/4 x 3/8 <b>E106</b> 13/16 x 7/16	0.78	0.88	1.44		
<b>E107 Trim</b> 	<b>E108 Trim</b> 	<b>E107</b> 3/4 x 1/2 <b>E108</b> 13/16 x 1/2	0.78	0.88	1.44		
<b>E110 Cove</b> 	<b>E111 Cove</b> 	<b>E101 Cove</b> 	<b>E110</b> 3/4 x 3/4 <b>E111</b> 5/8 x 5/8 <b>E101</b> 1/2 x 1/2	0.88 0.86 0.78	0.99 0.96 0.88	1.62 1.58 1.44	
<b>E120 Burlap</b> 	<b>E121 Burlap</b> 	<b>E120</b> 1 1/8 x 5/16 <b>E121</b> 1 1/2 x 5/16	0.88 0.96	0.99 1.08	1.62 1.76		
<b>Trim</b> 			<b>E129</b> 1 3/4 x 5/16	1.07	1.20	1.97	
<b>T &amp; G Paneling</b>  1 ft. = 0.24 sq/ft.			<b>E145</b> 2 7/8 x 3/8	2.14	2.41	3.94	
 <b>E112 Bolection</b>	 <b>E116 Bolection</b>	<b>E112</b> 1 1/8 x 1 <b>E116</b> 1 1/2 x 7/8	1.46 1.49	1.64 1.67	2.69 2.74		
 <b>Bolection</b>			<b>E113</b> 2 x 7/8	1.80	2.03	3.32	
 <b>Stringer Cap</b>			<b>E337</b> 1 3/4 x 11/32	1.83	2.06	3.36	
			<b>E561</b> 3/4 x 7/16	0.91	1.02	1.67	














6 Peacock Bay, St Catharines, Ontario, Canada L2M 7N8  
 Phone: (905) 937-3030 Fax: (905) 937-6799  
 Website: www.eastwoodspecialties.ca

<u>CABINET MOULDING</u>	<u>Code/Size</u>	<u>Poplar</u>	<u>Red Oak</u>	<u>H. Maple</u>		<u>Other</u>	
<b>Shaker Rail</b> 	<b>E142</b> 2 1/4 x 13/16	2.33	2.62	4.29		We have other species available in some of the profiles. Please inquire.	
<b>Valance</b> 	<b>E701</b> 3 x 3/4 <b>E702</b> 4 1/2 x 3/4	2.58 3.59	2.91 4.04	4.76 6.61			
<b>Valance</b> 	<b>E730</b> 3 x 1	3.60	4.05	6.64			
<b>Cabinet Mould</b> 	<b>E981</b> 2 7/8 x 3/4	2.58	2.91	4.76			
<b>Cabinet Mould</b> 	<b>E994</b> 4 3/8 x 7/8	3.59	4.04	6.61			
<b>Cabinet Cap</b> 	<b>E950</b> 2 1/4 x 13/16	2.02	2.27	3.71			
<b>Base Mould</b> 	<b>E736</b> 4 1/2 x 3/4	3.59	4.04	6.61			
	<b>E109</b> 1 x 1	1.49	1.67	2.74			
	<b>E150</b> 2 1/4 x 3/4	2.90	3.26	5.34			
	<b>E790</b> 5 1/2 x 1 3/4	11.90	17.86	19.95			
<b>E103 Panel Mould</b> 	<b>E104 Panel Mould</b> 	<b>E103</b> 1 1/8 x 5/8 <b>E104</b> 15/16 x 1/2	1.23 1.07	1.39 1.20	2.27 1.97		
<b>E115 Panel Mould</b> 	<b>E118 Panel Mould</b> 	<b>E115</b> 1 1/8 x 1/2 <b>E118</b> 1 1/8 x 9/16	1.07 1.07	1.20 1.20	1.97 1.97		



6 Peacock Bay, St Catharines, Ontario, Canada L2M 7N8  
 Phone: (905) 937-3030 Fax: (905) 937-6799  
 Website: www.eastwoodspecialties.ca

<i><b>D4S Material - Lengths 7' - 16'</b></i>	<i><b>Size</b></i>	<i><b>Poplar</b></i>	<i><b>Sanded 1 Face</b></i>		
			<i><b>* Red Oak</b></i>	<i><b>* H. Maple</b></i>	
 1 x 1	3/4 x 3/4	0.91	1.02	1.67	<b>Other species available upon request.</b>
 1 x 2	1 1/2 x 3/4	1.37	1.55	2.53	
 1 x 3	2 1/2 x 3/4	2.17	2.44	3.99	
 1 x 4	3 1/2 x 3/4	2.85	3.20	5.24	
 1 x 5	4 5/8 x 3/4	3.62	4.07	6.66	
 1 x 6	5 1/2 x 3/4	4.21	4.73	7.75	
 1 x 7	6 5/8 x 3/4	5.01	5.64	9.23	
 1 x 8	7 1/4 x 3/4	5.44	6.12	10.02	
 1 x 9	8 1/4 x 3/4	6.50	7.31	11.97	
 1 x 10	9 1/4 x 3/4	7.31	8.22	13.46	
 1 x 12	11 1/4 x 3/4	9.60	10.80	17.68	
<b>*Lengths longer than 12' are subject to a premium length charge*</b>					















<i><b>15/16" Stock Lumber</b></i>	
Poplar - Select & Better	5.50 / board foot
Red Oak - Select & Better	5.95 / board foot
Hard Maple - Select & Better	7.90 / board foot

<i><b>Extra Manching - Min. \$20.00</b></i>
<i>Available for \$0.25/bf per operation</i>
- redress to thinner specifications
- sand to 80 or 120 grit

<i><b>Lumber Specifications</b></i>
- All dressed to 15/16" and straight line ripped one edge
- Random width (5"-8") and random length (7'-10')

Special sort for wide widths, special lengths or premium color will be subject to 10% premium

6 Peacock Bay, St Catharines, Ontario, Canada L2M 7N8  
 Phone: (905) 937-3030 Fax: (905) 937-6799  
 Website: www.eastwoodspecialties.ca

<b>FLOORING MOULDINGS</b>		<b>Code/Size</b>	<b>Red Oak</b>	<b>H. Maple</b>	
		<b>E324</b> 4 1/2 x 1 1/16	7.94	12.99	 <b>ER520 Handrail</b> 2 3/4 x 1 5/8  <b>Poplar</b> 8.82 <b>R. Oak</b> 9.92 <b>H. Maple</b> 16.24
	<b>Nosing</b>	<b>E323</b> 3 1/2 x 1 1/16	6.52	10.67	
	<b>Transition</b>	<b>E317</b> 1 5/8 x 1/2	1.77	2.90	
	<b>Nosing</b>	<b>E330</b> 2 1/2 x 13/16	2.44	3.99	
	<b>Nosing</b>	<b>E331</b> 1 13/16 x 13/16	2.27	3.71	<b>Raw Unfinished Flooring for Landings</b>  FLR325-4 > 4' lengths FLR325-8RL > 8'-10' lengths <b>R. Oak</b> FLR325-4 \$2.95 lin/ft. FLR325-8RL \$3.40 lin/ft.  <b>H. Maple</b> FLR325-4 4.83 lin/ft. FLR325-8RL \$5.57 lin/ft.   R.Oak - FLR425-8RL \$4.59 lin/ft. H.Maple - FLR425-8RL \$6.16 lin/ft.
	<b>Reducer</b>	<b>E332</b> 1 3/4 x 5/8	2.06	3.36	
	<b>Carpet Reducer</b>	<b>E335</b> 1 13/16 x 3/4	2.06	3.36	
	<b>Flooring Reducer</b>	<b>E336</b> 1 13/16 x 3/4	2.06	3.36	
	<b>Nosing</b>	<b>E321</b> 1 1/4 x 1 1/16	1.63	2.67	
		<b>Panel blanks for tread recaps</b> 48 x 24 x 3/4	70.00	95.00	
			<b>Oak Recap Tread</b>		